

# Smart ANPR Camera Installation Guide

V1.0.1

Parts list:

- Smart ANPR Camera × 1
- Mounting bracket × 2
- Mounting plate × 1
- Mounting nut × 1
- Mounting screw × 1
- Mounting cap × 1
- Mounting ring × 1
- Mounting cap × 1
- Mounting ring × 1
- Mounting cap × 1
- Mounting ring × 1
- Mounting cap × 1

Dimensions (mm [inch]):

- 396.0 [15.59]
- 120.8 [4.76]
- 60.6 [2.39]
- 127.8 [5.03]
- 53.5 [2.107]
- ∅ 6.6 [0.26]
- ∅ 70.00 [2.76]

1

Diagram showing the camera being attached to the mounting nut. A T15 screwdriver icon indicates the tool used for this step.

2

Diagram showing the camera being attached to the mounting ring. An RST (Reset) button icon is shown.

2.1

Diagram showing the mounting plate being prepared with a hole. A PH3 screwdriver icon is shown.

2.1.1

Diagram showing the mounting plate being drilled with a 10mm diameter hole. A ∅10 mm hole icon is shown.

2.1.2

Diagram showing the mounting plate being aligned with the camera. A + sign icon indicates the alignment point.

2.1.3

Diagram showing the mounting plate being attached to the camera. A T15 screwdriver icon is shown.

2.1.4

Diagram showing the mounting plate being drilled with a PH3 screwdriver. A PH3 screwdriver icon is shown.

2.1.5A

Diagram showing the mounting plate being aligned with the camera. A warning icon and 'A B' labels are shown.

2.1.5B

Diagram showing the mounting plate being aligned with the camera. A warning icon and 'A B' labels are shown.

2.1.6

Diagram showing the mounting plate being attached to the camera. A T15 screwdriver icon is shown.

2.2

Diagram showing the mounting plate being attached to the camera. A ∅10 mm hole icon is shown.

2.2.1

Diagram showing the mounting plate being drilled with a 10mm diameter hole. A ∅10 mm hole icon is shown.

2.2.2

Diagram showing the mounting plate being aligned with the camera. A + sign icon indicates the alignment point.

2.2.3

Diagram showing the mounting plate being attached to the camera. A T15 screwdriver icon is shown.

2.2.4

Diagram showing the mounting plate being aligned with the camera. A PH3 screwdriver icon is shown.

2.2.5A

Diagram showing the mounting plate being aligned with the camera. A warning icon and 'A B' labels are shown.

2.2.5B

Diagram showing the mounting plate being aligned with the camera. A warning icon and 'A B' labels are shown.

2.2.6

Diagram showing the mounting plate being aligned with the camera. A T15 screwdriver icon is shown.